

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

December 11, 2008

John Gefferth, Engineer Consolidation Coal Company P.O. Box 566 Sesser, Illinois 62884

Subject: 2007 Annual Report Review, Emery Deep Mine, C/015/0015, Task ID # 3055

Outgoing File

Dear Mr. Gefferth:

The Division staff has completed the 2007 Annual Report Review. Enclosed is a copy of the review for Emery Deep Mine, C/015/0015 completed on December 11, 2008.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron Haddock **Permit Supervisor**

of Haddock

sqs Enclosure O:\015015.EME\FINAL\annualreportreviewletter.doc



Outgoing C0150015

2007 Annual Report Review

| Permittee: | Consolidation Coal Company | | | | | | |
|-----------------------|----------------------------|-------------------|--|--|--|--|--|
| Mine Name: | Emery Deep | | | | | | |
| Permit Number: | C015/0015 | | | | | | |
| Date Report Received: | July 1, 2008 | | | | | | |
| | | Date Completed | | | | | |
| Assigned Reviewer: | Karl R. Houskeeper | July 31, 2008 | | | | | |
| | Ingrid Wieser, Biology | December 11, 2008 | | | | | |

<u>Instructions:</u> The assigned inspector will review the Annual report during the third quarter complete inspection and provide a written determination (finding) on how the mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the mine lead notified. A copy of this review will be filed with the Inspection Report. Should any of the sections require additional technical analysis, the inspector will notify the permit supervisor so that it can be scheduled during the 4th quarter.

| SECTIONS TO REVIEW | | MITT NO | FINDINGS |
|--|--|-------------|---|
| Cover Sheet | | | |
| General Information | | | |
| Identification of other Permits | | | |
| Annual Impoundment Certification | | Ø | No MSHA impoundments. See Engineering Section for sediment pond certifications. |
| Annual Overburden, Spoil, Refuse, Floor, etc. Certified Report | | | Refuse pile certifications for 1 st through 4 th quarter 2007 are included in the annual report. The reports are P.E. certified. |
| Annual Technical Requirements (Commitments) | | | |
| Climatological | | \boxtimes | |
| Subsidence | | | A subsidence report is included in the 2007 annual report. The subsidence report consists of a data sheet that shows the location name, northing and easting coordinates, adjusted Oct. o6 elevations and the Nov. 07 elevation. The report did not contain a map that shows the location of the subsidence points in relationship to any underground workings. No visual determination can be correlated from the information given whether current mining areas have subsided. |
| Vegetation monitoring | | | |
| Raptor Survey | | | The 2007 annual report contains a raptor data table and corresponding map. Reviewed by Ingrid Wieser. An aerial raptor survey was conducted in 2007. The only tended Golden Eagle nest found in 2006 was still active and tended in 2007. Seven new Golden Eagle nests were located in 2007. There were four inactive nests, one tended, and two active nests, with one or two young sighted. Also, one active Raven nest was found with two feathered young. |
| Soils Monitoring | | \boxtimes | |
| Water Monitoring | | \boxtimes | |
| Geological/Geophysical | | \boxtimes | |

2007 Annual Report Review

| Engineering | | | | Annual certifications are included in the annual report for sediment ponds 1, 2, 3, 5, 6, & 9. The certifications do not include information for the 100% sediment elevation or the existing sediment elevation for any of the ponds as required by the Division. The report does give the design storage volumes and the 60% storage volume for each pond, however no correlation can be made from the information given to determine if the ponds have reached the 60 % clean level. Ponds 1, 2, 3, & 6 required maintenance or follow up items. Items 1&6 were addressed in the first quarter 0f 2008. Items 2 & 3 still need to be done. | | | |
|---------------------------------|--|-------------|--|---|--|--|--|
| Non-Coal Waste | | \boxtimes | | | | | |
| Abandoned Underground Equipment | | \boxtimes | | | | | |
| | | | | | | | |
| AVS; Legal/ Financial Update | | | | A certified copy of the Application for Certificate of Authority from the Utah Department of Commerce is included with the 2007 Annual Report. | | | |
| | | | | The annual report also contains a current Ownership and Control Report. | | | |
| Mine Sequence Map | | | | The mine map included in the 2007 Annual Report shows workings prior to 2007, mined areas during 2007, and proposed future mining. The map is P.E. certified. | | | |
| Other Information | | \boxtimes | | | | | |

O:\015015.EME\FINAL\Emery AR_07.doc